

ATTAR TEST REPORT NUMBER: 10/4240.2



This document is issued in accordance with NATA's accreditation requirements. The results of the tests, accreditation reador measurements included in this document are traceable to Australian/national standards. Accredit

3 August 2010

Total Pages: 1 Job No: M10/4240

OIL-WET RAMP SLIP RESISTANCE

Prepared for:	Gerflor Australasia	
	17 Cato Street	
	HAWTHORN EAST VIC 3123	
Attention:	Jutta Fronert	
Test Site:	ATTAR, Unit 12, 134 Springvale Road, Springvale.	
Test Date:	30 July 2010	
Manufacturer:	Gerflor	
Test Specimen, Size & Quantity Received:	Creation Clic flooring, 100x7.5 cm, 5 off supplied.	
Sampling & Direction of Testing:	Sampling conducted by client. Test conducted along the length of product, parallel with the grain.	
Test Personnel:	Marcus Braché & Daniel King	
Preparation:	3 off specimens mounted to 120x60 cm particle board, washed with pH neutral detergent, rinsed	
	with water then dried.	
Joint Width:	N/A	
Air Temperature:	22°C	
Test Standard:	AS/NZS 4586 - 2004 Slip resistance classification	
	of new pedestrian surface materials – Appendix D.	
Surface Structure :	Structured.	
Classification Criteria:	Corrected Mean Overall Acceptance Angle	Slip Resistance Assessment Group
(TABLE D3 in AS/NZS 4586- 2004)	6° to 10°	R9
	Over 10° to 19°	R10
	Over 19° to 27°	R11
	Over 27° to 35°	R12
	Over 35°	R13
Displacement Space:	Not Measured	
Displacement Space Assessment Group:	N/A	
Mean Overall Acceptance Angle:	13.5°	
Slip Resistance Assessment Group:	R10	

These results apply only to the specimens tested and it is recommended that before selection of flooring or paving materials the effect of service conditions, including maintenance procedures and wear on their slip-resistance be

checked.

NOTE: Any specimens supplied will be disposed of in two (2) months time, unless otherwise instructed.

ATTAR

Marcus Braché

Senior Engineering Technician

Approved Signatory

This report may not be reproduced except in its entirety.