

### Infrastructure Technologies

**Manufacturing Flagship**, Graham Road (PO Box 56), Highett, Victoria, Australia 3190
Telephone: 61 3 9252 6000 Facsimile: 61 3 9252 6244 Email: tiles@csiro.au Web: http://www.cmse.csiro.au

#### **Registered Testing Authority - CSIRO**

2 July 2015 Our Ref. EN13 / 415 03/0212

#### TEST REPORT No. 7435.2

Requested by: Gerflor Australasia P/L

17 Cato St Hawthorn East VIC 3123

on (date): 22 June 2015

Manufacturer: Gerflor

Product Desc.: Tarasafe Standard

Sampling details:

Where: Delivered Date: 22 June 2015

By whom: Courier How (methods): N/A

The results reported relate only to the sample(s) tested and the information received. No responsibility is taken for the accuracy of the sampling unless it is done under our own supervision. CSIRO cannot accept responsibility for deviations in the manufactured quality and performance of the product. While CSIRO takes care in preparing the reports it provides to clients, it does not warrant that the information in this particular report will be free of errors or omissions or that it will be suitable for the client's purposes. CSIRO will not be responsible for the results of any actions taken by the client or any other person on the basis of the information contained in the report or any opinions expressed in it. The reproduction of this test report is only authorised in the form of a complete photographic facsimile. Our written approval is necessary for any partial reproduction.

This test report consists of 3 pages

#### **SUMMARY OF SLIP RESISTANCE TESTS PERFORMED:**

Result Class

AS 4586:2013 Slip resistance classification of new pedestrian surface materials,

Appendix D: OIL-WET Ramp

Corrected mean overall acceptance angle: 12° R 10

In order to interpret the classifications, please refer to Standards Australia Handbook 198, An Introductory Guide to the Slip Resistance of Pedestrian Surface Materials, which recommends minimum classifications for a wide variety of locations.

It is important to realise that test results obtained on unused factory-fresh samples may not be directly applicable in service, where proprietary surface coatings, contamination, wear and subsequent cleaning all influence the behaviour of the pedestrian surface.



### Infrastructure Technologies

**Manufacturing Flagship**, Graham Road (PO Box 56), Highett, Victoria, Australia 3190
Telephone: 61 3 9252 6000 Facsimile: 61 3 9252 6244 Email: tiles@csiro.au Web: http://www.cmse.csiro.au

REPORT NO: 7435.2 Page 2 of 3

ISSUE DATE: 2 July 2015
MANUFACTURER: Gerflor

PRODUCT DESC: Tarasafe Standard

# SLIP RESISTANCE CLASSIFICATION OF NEW PEDESTRIAN SURFACE MATERIALS

	(	OIL-WET RAMP TEST METHOD		
TEST CARRIE AS 4586:2013	D OUT IN ACCORDANCE (Appendix D)		st Date: 2 July 2015	
Location: S	Slip Resistance Laboratory	Test conducted by: KH,	AG	
Sample Fixed				
Joint width: 0 r	nm			
Surface structu	[X ] Pro	nooth ofiled ructured		
RESULTS				
Corrected mean overall acceptance angle: 12 °				

not tested

## CLASSIFICATION:

**Displacement space:** 

Slip Resistance Assessment Group: R 10

Displacement Space Assessment Group: -

Test shoe used: Uvex Athletic



### Infrastructure Technologies

**Manufacturing Flagship,** Graham Road (PO Box 56), Highett, Victoria, Australia 3190
Telephone: 61 3 9252 6000 Facsimile: 61 3 9252 6244 Email: tiles@csiro.au Web: http://www.cmse.csiro.au

REPORT NO: 7435.2 Page 3 of 3

ISSUE DATE: 2 July 2015 MANUFACTURER: Gerflor

PRODUCT DESC: Tarasafe Standard

Date and Place 2 July 2015, Highett, Vic

Name, Title and Digital Signature:

KHANH HO Technical Officer

Tel: 61 3 92526119 Fax: 61 3 92526244 Email: Khanh.Ho@csiro.au